



Date: 12/29/25 13:49 Yard: LAREDO DISTRIBUTION CENTER Location:

HDI2500011

ARRIVAL

INSPECTION: C-TPAT +

Truck information		Trailer information		Tires		
Driver	DRIVER	Trailer	PENDIENTE	Position	Brand	Serie
License	LICENCIA	Plates	PL CAJA	Position #11	marca	111111
Company	ALA AUTOLINEAS AMERICA	State	TAMAULIPAS	Position #12	marca	22222
Truck #	000	Status	CARGADA	Position #13		
Truck plates	PL CAMIÓN	Seal	SELLO1,SELLO2	Position #14		
		Load #		Position #15		
		Created by	SISTEMAS MASTER	Position #16		
				Position #17		
				Position #18		

C-TPAT (17 Points)

Tractor		Trailer	
Bumper	No	Exterior undercarriage	No
Engine	No	Doors	No
Tires	Yes	Interior floor	No
Interior floor	No	Side walls	No
Fuel tanks	No	Front wall	No
Cabin	No	Ceiling	No
Air tanks	No	Refrigeration unit	No
Chasis	No	Mufflers	No
Fifth wheel	Yes		

Comments:

INSPECTION

Lights		Accessories	
Rear amber lights 2	No	Ruber seal 2	No
Front lights 2	No	Glad hands 2	No
Rear lights 5	No	Couplings 2	No
ABS lights	No	Mud flaps 2	No
Rear stop & signal lights 4	No	Dolly handle	No
License plate lights	No	Glove compartment	No
Reflective lights	No	Hinges	No

Comments:

Observations:

Photos

FG

SISTEMAS MASTER

FCh

DRIVER



FG

SISTEMAS MASTER

#Ch

DRIVER