



Date: 12/31/25 10:38 Yard: LAREDO DISTRIBUTION CENTER Location:

HDI2500013

ARRIVAL

INSPECTION: BÁSICA

Truck information

Driver	DRIVER
License	LICENCIA
Company	FEMA
Truck #	0002
Truck plates	PLACAS CAMION

Trailer information

Trailer	J BASICA
Plates	PLACAS CAJA
State	BAJA CALIFORNIA SUR
Status	CARGADA
Seal	SELLO1,SELLO2
Load #	
Created by	SISTEMAS MASTER

Status Inspection

Trailer condition	Good
Tire condition	Good

OBSERVATIONS CAJA EN BUEN ESTADO

PHOTOS



EGuardia

SISTEMAS MASTER

FCcho

DRIVER