



Date: 01/05/26 10:06 Yard: LAREDO DISTRIBUTION CENTER Location: YARDA Z # HDI2600001

**RELEASE**

**INSPECTION: C-TPAT +**

**Truck information**

Driver DRIVER  
 License LICENCIA  
 Company FEMA  
 Truck # 0000  
 Truck plates PL CAMION

**Trailer information**

Trailer PRUEBAACARGADA  
 Plates PL CAJA  
 State ALASKA  
 Status VACÍA  
 Seal N/A,N/A2  
 Load # SALIDA  
 Created by SISTEMAS

**Tires**

Position	Brand	Serie
Position #11	marca	serie1111
Position #12	marca	serie2222
Position #13		
Position #14		
Position #15		
Position #16		
Position #17		
Position #18		

**C-TPAT (17 Points)**

**Tractor**

Bumper Yes  
 Engine Yes  
 Tires Yes  
 Interior floor Yes  
 Fuel tanks Yes  
 Cabin Yes  
 Air tanks Yes  
 Chassis Yes  
 Fifth wheel Yes

**Trailer**

Exterior undercarriage No  
 Doors No  
 Interior floor No  
 Side walls No  
 Front wall No  
 Ceiling No  
 Refrigeration unit No  
 Mufflers No

**Comments:**

**INSPECTION**

**Lights**

Rear amber lights 2 No  
 Front lights 2 No  
 Rear lights 5 No  
 ABS lights No  
 Rear stop & signal lights 4 No  
 License plate lights No  
 Reflective lights No

**Accessories**

Ruber seal 2 No  
 Glad hands 2 No  
 Couplings 2 No  
 Mud flaps 2 No  
 Dolly handle No  
 Glove compartment No  
 Hinges No

**Comments:**

**OBSERVATIONS**

OBSERVACIONES EN LA SALIDA DE PATIO TODO OK

**PHOTOS**

*F Guar*

**SISTEMAS**

*HV Ma*

**DRIVER**