



Date: 01/07/26 09:35 Yard: LAREDO DISTRIBUTION CENTER Location:

HDI2600002

ARRIVAL

INSPECTION: C-TPAT +

Truck information

Driver SISTEMAS
License LICENCIA
Company FEMA
Truck # 000
Truck plates PLACAS CAMIÓN

Trailer information

Trailer PRUEBAS 01
Plates PLACAS CAJA
State TAMAULIPAS
Status CARGADA
Seal PENDIENTE
Load #
Created by SISTEMAS MASTER

Tires

Position Brand Serie
Position #11 gy 0006
Position #12
Position #13
Position #14
Position #15
Position #16
Position #17
Position #18

C-TPAT (17 Points)

Tractor

Bumper No
Engine No
Tires No
Interior floor No
Fuel tanks No
Cabin No
Air tanks No
Chassis No
Fifth wheel Yes

Trailer

Exterior undercarriage No
Doors No
Interior floor No
Side walls No
Front wall No
Ceiling No
Refrigeration unit No
Mufflers No

Comments:

INSPECTION

Lights

Rear amber lights 2 No
Front lights 2 No
Rear lights 5 No
ABS lights No
Rear stop & signal lights 4 No
License plate lights No
Reflective lights No

Accessories

Ruber seal 2 No
Glad hands 2 No
Couplings 2 No
Mud flaps 2 No
Dolly handle No
Glove compartment No
Hinges No

Comments:

OBSERVATIONS

OBSERVACIONES GENERALES

PHOTOS



Handwritten signature of SISTEMAS MASTER

SISTEMAS MASTER

Handwritten signature of SISTEMAS

SISTEMAS