



Date: 01/12/26 17:07 Yard: LAREDO DISTRIBUTION CENTER Location: # HDI2600004

ARRIVAL

INSPECTION: BÁSICA

Truck information

Driver SISTEMAS
License LICENCIA
Company FEMA
Truck # TCYV
Truck plates G5G5

Trailer information


Trailer FRCR
Plates 5G6H
State AGUASCALIENTES
Status CARGADA
Seal
Load #
Created by SISTEMAS MASTER

Status Inspection

Trailer condition Good
Tire condition Good

OBSERVATIONS

PHOTOS



Handwritten signature of SISTEMAS MASTER

SISTEMAS MASTER

Handwritten signature of SISTEMAS

SISTEMAS