



Date: 01/13/26 16:29 Yard: LAREDO DISTRIBUTION CENTER Location:

HDI2600008

ARRIVAL

INSPECTION: C-TPAT +

Truck information

Driver DRIVER
License LICENCIA
Company 1 LINE TRANSFER
Truck # YFYCF
Truck plates

Trailer information

Trailer HVUGU
Plates
State
Status CARGADA
Seal
Load #
Created by SISTEMAS MASTER

Tires

Position	Brand	Serie
Position #11		
Position #12		
Position #13		
Position #14		
Position #15		
Position #16		
Position #17		
Position #18		

C-TPAT (17 Points)

Tractor

Bumper Yes
Engine Yes
Tires Yes
Interior floor Yes
Fuel tanks Yes
Cabin Yes
Air tanks Yes
Chassis Yes
Fifth wheel Yes

Trailer

Exterior undercarriage Yes
Doors Yes
Interior floor Yes
Side walls Yes
Front wall Yes
Ceiling Yes
Refrigeration unit Yes
Mufflers Yes

Comments:

INSPECTION

Lights

Rear amber lights 2 Yes
Front lights 2 Yes
Rear lights 5 Yes
ABS lights Yes
Rear stop & signal lights 4 Yes
License plate lights Yes
Reflective lights Yes

Accessories

Ruber seal 2 Yes
Glad hands 2 No
Couplings 2 Yes
Mud flaps 2 Yes
Dolly handle No
Glove compartment Yes
Hinges Yes

Comments:

OBSERVATIONS

PHOTOS



SISTEMAS MASTER

DRIVER