



Date: 01/13/26 16:33 Yard: LAREDO DISTRIBUTION CENTER Location:

HDI2600009

ARRIVAL

INSPECTION: C-TPAT +

Truck information

Driver	SISTEMAS
License	LICENCIA
Company	1 LINE TRANSFER
Truck #	NHHJV
Truck plates	UFUGUGU

Trailer information

Trailer	HXHCJC
Plates	UGUGUG
State	AGUASCALIENTES
Status	CARGADA
Seal	HIIBIHI,IVKVK
Load #	KVKV
Created by	SISTEMAS MASTER

Tires

Position	Brand	Serie
Position #11	fire	
Position #12		
Position #13		
Position #14		
Position #15		
Position #16		
Position #17		
Position #18		

C-TPAT (17 Points)

Tractor

Bumper	Yes
Engine	Yes
Tires	Yes
Interior floor	Yes
Fuel tanks	Yes
Cabin	Yes
Air tanks	Yes
Chasis	Yes
Fifth wheel	Yes

Trailer

Exterior undercarriage	Yes
Doors	No
Interior floor	Yes
Side walls	Yes
Front wall	No
Ceiling	Yes
Refrigeration unit	No
Mufflers	Yes

Comments:

INSPECTION

Lights

Rear amber lights 2	Yes
Front lights 2	Yes
Rear lights 5	Yes
ABS lights	No
Rear stop & signal lights 4	Yes
License plate lights	Yes
Reflective lights	Yes


Accessories

Ruber seal 2	Yes
Glad hands 2	No
Couplings 2	Yes
Mud flaps 2	Yes
Dolly handle	Yes
Glove compartment	Yes
Hinges	Yes

Comments:

OBSERVATIONS

PHOTOS



SISTEMAS MASTER

SISTEMAS